## **Vinyl Cutter Basics**


Inspiration Station: Geauga County Public Library's Maker Space Instructions

#### **Table of Contents**

- Introduction.....1
- Load the Material..... 2
- Perform a Test Cut...... 5
- Set the Origin...... 6

- Create a Cutting Project... 7
- Save your Cut Job..... 11
- Perform Cutting...... 11
- Remove the Material...... 12

### Introduction



The GS-24 CAMM-1 vinyl cutter can:

- Cut characters and shapes cleanly.
- Make one-color stickers.
- Cut perforated lines on a variety of materials.
- Handle large output designs smoothly.

#### Loadable Material Sizes

Width	Length	
2  28  in share  (50  700  mm)	Flat Material: 4 inches (100 mm) or more	
2 – 28 inches (50 – 700 mm)	Roll Material: No restriction	
	we adde the structules are a 44 lbs (Files)	

CAUTION: Never load media that weighs over 11 lbs (5 kg)

#### Cuttable material thickness: 0.1 mm or less

**Maximum material thickness (including carrier paper):** 0.3 mm of less. Material up to 1 mm thick can be loaded depending on the blade.

#### Cuttable area:

Width: 22 inches (584 mm) Length: 984 inches (25000 mm) or 82 feet

Accepted File types: BMP, JPG, JPEG, STX, AI, EPS, and PNG. JPG, JPEG, and PNG work best.


#### Load the Material

Always load the material first before doing anything with the design. The machine needs to know the size of the media before the design can be cut.

1. Lower the loading lever.




- 2. Load the material.
  - a. With the short edge of the material toward the front, pass the material through the machine.
  - b. If loading heat transfer vinyl, make sure the material is shiny side down. The shiny side is a heat transfer mask for transferring the design to fabric.
- 3. Set the material in the position shown.
  - a. The position differs according to the size of the material loaded.
  - b. Focus on the right side of the media. The left side purposefully has extra grit rollers to adapt to different sized media.




Grit Mark

- 4. Move the pinch rollers to the edges of the material so that each one is within the grit marks.
  - a. The pinch rollers must not extend beyond the grit marks.




5. Align the left edge of the material so that it lies approximately parallel to the guidelines.




Guide Lines


6. Raise the loading lever. The material is secured in place.



- 7. Turn on the machine
  - a. Make sure the machine is plugged in.
  - b. Plug the USB cord into the laptop
  - c. Make sure the wheels are locked (at least 2 of them) to avoid shifting while cutting.
  - d. Press the **Power** button.



8. Select Sheet by pressing the down arrow to the proper material (Roll, Edge, or Piece).



- a. Roll: for rolled vinyl, the machine will measure the width and not the length.
- b. Edge: for any type of vinyl, as it only measures the width and not the length (least popular).
- c. Piece: measures the width and the length. Great for small sheets of vinyl.
- 9. Press Enter.
  - a. The cutting carriage moves to the left pinch roller position, and the material moves forward and backward.
  - b. The cuttable width and length (if applicable) will appear on the display.

W	:180mm	
L	: 250mm	


10. After the operation stops, check that the material has not come loose.




### **Perform a Test Cut**

Carry out a cutting test to check the quality of the material before you perform your actual project. If you already know the proper pen force for your media, you can skip to Create a Cutting Project.


1. Check that the **Pen Force** is set in the center at **zero (0)**.



Hold down the **Test** button for one second or longer, until the machine starts to move.
 a. The test pattern will cut.



3. Press the **Down** button to feed the material forward.



4. Peel off Circle 1, then peel off the Rectangle 2. You should be able to see faint traces on the material's carrier paper and all pieces should peel off easily.



5. If the cut was not clean, increase the **Pen Force**. If the cut is too distinct or too deep, decrease the **Pen Force**.


### **Set the Origin**

OPTIONAL: If using the same media for multiple projects, you can change the origin – where the blade begins cutting a job. You also may want to do this after doing a test cut. Otherwise skip to Create a Cutting Project.

1. Press the Right and Up arrow buttons to move the cutting carriage to the location you want to set as the origin.



2. Hold down the **Origin** button for at least one second.



a. The display will flash "Origin Set"




3. You are ready to cut.

### **Create a Cutting Project**

1. Click on **CutStudio** on the desktop:



2. Click on File and then click Cutting Setup.



3. Make sure the name **Roland GS-24** is the chosen Printer.

	Cut Setting	
Printer Name( <u>N</u> )	Research 28	Property
Status:	невоу	

4. Under Media Size, click Change.

Printer Name(N)	Point 1828.		•	Property
Status: Type: Port:	Ready			
Comment:				
A	- Media Size	8.2717 inch		

- 5. Click Get from Machine then click OK
  - a. The cuttable area is displayed.
  - b. This is the number that you received after loading the material.

Properties	×	
Size Settings Options		
Cutting Area Width : 8.27 Length : 11.73 Get from Machine	Rotate © Off © 90deg	
Unit : C Millimeters	Roland About	
Inches	OK Cancel H	elp

6. Click **OK** to close the Cut Setting window. The cutting area is set.

Perforation length:	0.7874	inch	
Half-cut length:	0.0197	inch	
Half-cut force:	1	gf	Get from Machine

7. The origin point is in the lower left of the cutting area.

譜 Uncitied - Cu	tStudie						-		×
	8 .	Cutting Prot			Copy	Et Mest		Papertes	_
<u>}</u> 				1					Î
00*7~		←	- Cu	tting a	area	->			
	(	3-		v					

8. Create your design. Or you can open a design you already made by clicking File → Open.
a. To upload an image, click Import.

🖹 Unt	itled - Cu	utStudio	)			
File	Edit Vie	w For	mat Ob	ject Help		
New	Open	Save	Import	Cutting	Print	U

b. Choose your file from your USB drive and click **Open**.


i. Accepted File types: BMP, JPG, JPEG, STX, AI, EPS, and PNG. JPG, JPEG, and PNG work best.



9. Your image will appear in the cut area.




- 10. Change the image into a cut line by clicking **Object** then **Image Outline**.
  - a. A new window will open.



b. Click **Extract Contour Lines** then click **OK**. You can edit the lines by changing the Alignment Image Density or Remove Thin Lines depending on your image.


Extract Contour Lines	Alignment Image Density	Items Displayed
Welding Of Contour	Light Dark	
	🔲 Remove Thin Lines	
	Small Large	
		OK Cancel

c. There are now cut lines over your image that the vinyl cutter will follow.




11. Click the **Move** button in the Toolbar to place the design in the bottom left corner near the origin.

14




b. Positioning the design near the bottom of the cutting area saves material.



# Save your Cut Job

1. If you want to save the design for another cutting session, click the **Save** button.



2. Select your USB drive and then click Save. It will save as a CutStudio document file (CST).

DE (E:)     IT (F:)     ES (G:)	v < >
File <u>n</u> ame:	Untitled.cst V
Save as type:	CutStudio Document (*.cst) V
) Hide Folders	Save Cancel

## **Perform Cutting**

1. Click the **Cutting** button.




- 2. Check that the cutting settings fit what you want. Then click **OK**.
  - a. Cutting data is sent from the computer to the machine and cutting starts.


Overlap Outling:	Machine settings	-				
Ouelity:	Machine settings	•				
Cutting Conditions						
Cutting force:		ø				
Cutting speed.		cn/sec				
Blade offset.		mm				
Performed Cutting Condi	itions			CALE		
Perforation length:		mm		SALE		
Hall-out length:		mm				
Hell-cut force.		gt.				
			🔽 Out in color order		Move to Orig	in .
			~ I ~ I			

#### **Remove the Material**

1. Press the **Menu** button several times until the display reads "Unsetup"




2. Press Enter.




a. The carriage returns to the home position




3. Lower the loading lever and remove the material.



4. To remove the cut area *only*, use a utility knife or similar tool to cut along the knife guide.



5. Turn off the machine by holding down the **Power** button.



6. Unplug the machine and place it back in its original location.